



# Delo® Testimonial: Freestate Petroleum Distributors

## Achieves 1,000,000+ kilometres in a Freightliner® Truck using Delo® family of products.



Freestate Petroleum Transportation has been hauling petroleum products for over 20 years in the South African market and has grown to over 40 trucks in their fleet. They operate under severe conditions in the South African market with Freightliner trucks and Cummins ISX 500 engines burning 500ppm sulphur diesel fuel under heavy loads of 56,000kg. They recently achieved 1,000,000+ km of total mileage in one of their trucks and wanted to see how the Delo® family of products protected the engine since its first use over 8 years ago.



Jean Snyman

Chevron and Freestate Petroleum personnel agreed to conduct an engine teardown and inspection of the Cummins ISX 500 engine in Bloemfontein, South Africa at the local OE Dealer. The engine burns diesel with sulphur content up to 500 parts per million and uses Caltex Delo® 400 Multigrade SAE 15W-40 and Delo® XLC Extended Life Coolant.

**“We’re very excited about the performance of this truck. It was the first truck in our fleet that we acquired about 8 years back and it’s done about a million km and on the performance of this truck we acquired additional trucks. All our trucks run on Delo® 400 and their family of products,” says Jean Snyman, owner of Freestate Petroleum Distributors.**



The final inspection overall showed a clean engine with minimal deposits and wear on the key engine components. The pistons showed minimal deposit buildup on the crown and top ring land zone. The camshaft lobes showed excellent wear protection and no visible wear scars on rollers or rocker arms. Bearings also were in very good shape with only small amounts of overlay removal – excellent for an engine with this many kilometres at high load.

**“It’s hard to believe that this has been a vehicle that has gone over a million km with loads up to 56,000kg. There is minimal removal of overlay and just a couple of scratches where debris has gotten into the oil. This is reflective of the performance of Delo® 400,” says John Green – Chevron Technical Specialist.**



Johan Liebenberg

Delo® XLC Extended Life Coolant also helps protect the engine cooling system on this truck. Inspection of the cooling system revealed that Delo® XLC prevented cavitation pitting on the liners and water pump impeller. The engine cooling system showed no signs of deposit buildup or corrosion on key metal parts.

**“We’ve seen the condition of the million km engine only running on Delo® 400 and Delo® XLC Extended Life Coolant. The way they protected the engine, it would be hard not to recommend these products to any other customer,” says Johan Liebenberg, Sales Manager OE Dealer.**

To learn how Delo’s family of products can help you go further, visit [CaltexDelo.com](http://CaltexDelo.com).



### Top Deck

Very clean and shows no visible deposit or sludge buildup indicating excellent dispersant protection offered by Delo® 400.



### Connecting Rod Bearings

Very good shape showing minimal overlay removal and no copper underlay showing.



# Delo® Let's go further.™